Declassified in Part - Sanitized Copy Approved for Release 2013/12/18: CIA-RDP82-00457R007800600008-9 CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS OIL CENTRAL INTELLIGENCE AGENCY REPORT INFORMATION REPORT CD NO. DATE DISTR. 1 June 1951 Germany (Russian Zone) COUNTRY 50X1-HUM Atche Schifferevisious-und SUBJECT NO. OF PAGES Klassifikationsgesellschaft (DSKG) CONFIDENTIAL NO. OF ENCLS. PLACE **ACQUIRED** SUPPLEMENT TO DATE OF 50X1-HUM REPORTIO. INFO. This Document Contains information affecting the national deferse of the Brittle States Cittur for Electric of the Editologic act so t. s. c., 31 and 32. As alexaded. Its transmission of the revention of the Contents in any Electric of the Colling Tolking of the Libertle by Law Electrocity of this Fools is possible to THIS IS UNEVALUATED INFORMATION 50X1-HUM Effective 1 January 1951, West-Berlin firms were barred, by law, from work in the Soviet Zone of Germany. : -2. Shippards and other plants in the Soviet Zone of Germany were instructed that beginning 1 January 1951, the ship acceptance business of the Germanischer Lloyd (Gorman Ship-Survey and Classification Company) was delegated to the Deutsche Schiffsrevisions- und Klassifikationsgesellschaft (DSKG), a public corporation in Miersdorf near Zeuthen. 3. According to the Ministerial blatt (Ministerial Gazette) No. 8 of 15 May 1950, the DSKG was established on 1 April 1950. Head manager of the company is one. Daehn (fnu). Because personnel was lacking the DSKG could not start work in the shippards and plants until late 1950. A member of the DSKG said, at the end of January 1951, that the company was still lacking about 30 persons. In late January 1951, the staff numbered 22 persons. Applicants were given a three-month training course. During training, they receive 550 eastmarks a month, and, after a probational period of three months as inspectors in a shippard, they are paid 850 eastmarks. Acceptance inspections in the shipyards and plants are based on directives issued by the Cermanischer Lloyd. The shipyards and plants had procured these directives from the Germanischor Lloyd prior to the change in control.  $l_{
m to}$  The shippards were dissatisfied with these new inspectors who were said to be complete failures in practice. The Rosslauer Schiffswerft, for example, hired two permanent employees of the Deutsche Schiffahrts- und Umschlagsbetriebs-Gesellschaft (German Shipping and Transshipment Operating Company) (DSU) at Wallwitzhafen and Aken on the Elbe River for acceptance inspections, and this proved very successful. The DSU is an old firm which formerly surveyed repairs to inland vessels and also made acceptance inspections in compliance with the directions of Germanischer Lloyd, It is said that the DSU will be incorporated in the DSKG. 5. The Soviet control commissions in the shippards are hesitant to recognize the DSKG and some of them even insist on acceptance by Jermanischer Lloyd. Therefore, a number of Germanischer Lloyd agents are still working with the Neptun Shipyard in Rostock, although this is against the law. In the other shippards, the new ships, if they have been built for expert or CONFIDENTIAL CLASSIFICATION SECRET/CONTROL OFFICIALS ONLY NSRB DISTRIBUTION STATE X NAVY X AIR # X FBI 📑 Berlassified data, Change i Tar Auth.: KR 50X1-HUM Tale: \_10\_0

CIA-RDP82-00457R007800600008-9

Declassified in Part - Sanitized Copy Approved for Release 2013/12/18

Declassified in Part - Sanitized Copy Approved for Release 2013/12/18: CIA-RDP82-00457R007800600008-9

Secret/Control	47800	v.s.	OFFIC TALS	ONLY
----------------	-------	------	------------	------

ENTRAL INTEXLIGENCE AGENCY	
----------------------------	--

50X1-HUM

on reparations account, are taken over by a control commission of the Soviet Sea-Register after they have been accepted by the DSKO.

- 7. The newly-built vessels for the Soviet Zone of Germany are accepted by the DSKG in compliance with the directions of Germanischer Lloyd. This procedure was established because Germanischer Lloyd is recognized internationally and the DSKG is not. The Cermanischer Lloyd knows of cases where wessels passed by the DSKG were refused assistance and were not entrusted with return freight in Danish or Swedish territorial waters and harborse Swedish tankers, for instance, refuse to deliver fuel oil to these vessels.
- 8. As a result of the shortage of personnel in the DSKG and insufficient training of the inspectors, some shippards suffered delays of delivery dates. These delays have caused some companies, including the Rosslau Shippard and the Thaelmann Shippard in Brandenburg, to file complaints with the Government about this situation.

CONFIDENTIAL

SECRET/CONTROL/US OFFICIALS ONLY